

PIPES – AUDI-VW – VORST – BELGIUM

In 2017 the **AUDI-VW** Car Company decided to repair their cold water piping located in their assembling unit of Vorst, Belgium, with **ZINGA** as stand-alone system.



Before repairs with ZINGA



After repairs with ZINGA



System:

Blasting with quartz to SA 2.5
ZINGA 2 x 60 µm DFT (brush)