



DANZAS - BELGIUM

Pictures of the application of ZINGA (25 to 40 μm) and Sealer Washprimer on a truck of the brand Scania in January 2001. The proprietor of the truck is the company Danzas. The coating was applied by Saey's.

Rust formation on the chassis of the truck.



And on the back of the truck.





After sandblasting ...



System :

ZINGA 1 x 25 to 40 µm

Followed by a Wash Primer application



And finalised with a black finish coat

