

## HELL BRIDGE – TRONDHEIM – NORWAY

In 2000, **ZINGA** was applied on the steel structures of the **Hell Bridge** in Norway.  
The bridge was inspected in 2007 and no touch-ups were required.



System:  
Blasting to SA 2,5 and Rz 50-70µm  
ZINGA            2 x 60 µm DFT

## HELL BRIDGE – TRONDHEIM – NORWAY

On 13 November 2018, **18 years after the original application**, a visual inspection was carried out by **ZINGA Belgium and ZINGA Norway**.

Not any corrosion nor any adhesion defects could be spotted.



Seaside view