

3. Reference information (specifically Marine environments)

- *Kalvoya Bridge (Norway)*
In 1985
ZINGA 2 x 60 μ m DFT
In 1995 an independent inspection showed no need for repairs.
In 2010 only 30 μ m ZINGA had sacrificed itself to protect the metal underneath

